


## JVOP-181 USB Driver Installation for Windows Vista, Windows 7 – 32/64 bit

Follow these steps to install the JVOP-181 (Y-Stick) USB driver for Windows 32 or 64 bit.

**Step 1:** Start your computer

**Step 2:** Plug JVOP-181 (Y-Stick) into computer


**Step 3:** Wait until Windows reports that it is not able to find the driver.




**Step 4:** Click Windows Start button and right mouse click on "Computer", select properties.

**Step 5:** Click on Device Manager and the device manager window opens.


Next select the **Unknown Device**, right mouse click and select Update Driver Software.




**Step 6:** Click on Browse my Computer for Driver Software




**Step 7:** Select folder that contains the JVOP-181 (Y-Stick) Driver and click next.



**Step 8:** Click Install button to install the driver.




**Step 9:** Driver is now installed



**Important Note:** Follow steps A through D in case the driver did not install properly or Windows automatically selected another driver.

**Step A:** Right mouse click on the JVOP-181(Copy Unit) and select Uninstall.



**Step B:** Next click Ok in the dialog box.



**Step C:** Unplug the JVOP-181 (Y-Stick) from your computer and wait 10 sec then plug the JVOP-181 (Y-Stick) back in.

**Step D:** Repeat steps 1 though 9 above to install the driver.